

Surface Preparation and Adhesive Application

Surface Preparation & Adhesive Application

Step 1: Surface Inspection

- Clean and dry surface
- Remove rust and debris

Step 2: Primer Application

- Apply per manufacturer specs

Step 3: Adhesive Application

- Use IPS recommended adhesives
-

